

**polkaudio**  
the speaker specialists®

San Diego, CA 92154-7408

tel (619) 661 6204

fax (661) 661 8074

[www.polkaudio.com](http://www.polkaudio.com)

Dear Polk Customer,

Thank you for choosing Polk Audio for replacement tweeters for your Polk Audio speakers. You are receiving a replacement tweeter with a part number of RD0194-1, which is engineered to be the equivalent of the SL1000 and SL2000, 1" dome tweeters found on many of our Monitor, RTA and SDA series of speakers. The mechanical and electrical characteristics are the same, however there might be some relatively minor physical differences which can easily be dealt with. It is possible the four, corner located, mounting holes, on this tweeter, might not perfectly line up with the original screw hole locations. Most of the time, there is enough play in the positions of the holes that if the screws were placed at a slight angle they would then seat properly. If you don't feel there will be enough play in the screw hole, it might be necessary to drill small "pilot" holes to allow the screws to seat properly. Once done the new tweeter should produce the same high quality sound that you enjoyed originally. If you have any questions, please feel free to contact Polk Customer Service at 1-800-377-7655 available from Monday through Friday 9:00 AM until 6:00 PM EST. or 1-888-267-5495 Monday through Friday 8:00AM until 4:00PM PST.

Polk Audio

RM0195-1